

	Type	L #	Hits	Search Text
1	IS&R	L10	128	(301/37.101).CCLS.
2	IS&R	L11	374	(40/587).CCLS.
3	IS&R	L12	863	(40/591).CCLS.
4	IS&R	L8	40	(301/37.108).CCLS.
5	BRS	L1	584	301/37.101
6	BRS	L2	12	301/37.105
7	BRS	L3	30	301/37.23
8	IS&R	L4	128	(301/37.101).CCLS.
9	IS&R	L5	154	(301/37.105).CCLS.
10	IS&R	L6	173	(301/37.23).CCLS.
11	IS&R	L7	39	(301/37.102).CCLS.
12	IS&R	L9	39	(301/37.102).CCLS.
13	IS&R	L13	114	(301/37.25).CCLS.
14	IS&R	L14	0	("wheelsamespinnersamemotor").PN.
15	BRS	L15	468	wheel same spinner same (drive or motor)

	DBs	Time Stamp	Comm en ts	Error r e f i n t i o n	Error r e f i n t i o n
1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:09			
2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:09			
3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:09			
4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:10			
5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:11			
6	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:13			
7	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:13			
8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:14			
9	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:16			
10	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:16			
11	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:17			
12	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:19			
13	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:19			
14	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:27			
15	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:27			

Type	L #	Hits	Search Text
16	BRS	L16	223 wheel same spinner with (drive or motor)

	DBs	Time Stamp	Co mm en ts	Er ro r en ti on	De fici ni ti on	Er ro rs
16	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/09/01 10:28				